

Other Exterior Door(s)

Game room exterior door striker plate is missing or not installed. Replacement needed.



Windows	
Windows	Window frames, screens and exterior finish are in satisfactory condition consistent with their age and quality.
Patio	
Patio Type	Screen Enclosed Lanai.
Patio	Patio appears to be in satisfactory condition.
Porch	
Porch	Porch appears to be in satisfactory condition.
Exterior Steps & Stairs	

Steps and Stoops

Exterior steps and stoops appear to be in satisfactory condition.