

levels were found. Recommend evaluation and repair by a licensed roofing contractor.



Roof Soffit & Fascia

Soffit and fascia appear to be in satisfactory condition and show only signs of normal wear.

Attic

Attic Access Point
Attic Access?

Garage.
Remote areas of the attic were not accessible or visible due to roof design and/or location of duct system.

Attic Insulation

Generally as a whole, fiberglass insulation appears to be functional, in satisfactory condition consistent with its age and quality.

Attic Ventilation

Installed attic vents appear to be functional, in satisfactory condition.

Gutter(s) & Downspout(s)

Gutter(s) & Downspout(s)

Generally as a whole, gutters and downspouts appear to be functional, in satisfactory condition.